



V E N M A R[®]

WARNING

Do you own an air exchanger manufactured between 1983 and 2001, or between October 2006 and August 2007?

Venmar Ventilation announces that it is voluntarily expanding its **Safety Upgrade Program**. An unlikely series of circumstances could lead to a motor overheating, which may result in a **potential fire hazard**.

Does this apply to your product?

Visit our website at

www.venmar.ca

and click on the icon



or call us at

1 866-441-4645